

FC11 - <offline>

"Warn quantity's program"

Name:
Author: Cristian **Family:**
 Version: 0.1
 Block version: 2
Time stamp Code: 05/02/2008 09:21:02 AM
 Interface: 01/19/1999 11:43:24 AM
Lengths (block/logic/data): 00188 00078 00000

Name	Data Type	Address	Comment
IN		0.0	
OUT		0.0	
IN_OUT		0.0	
TEMP		0.0	
RETURN		0.0	
RET_VAL		0.0	

Block: FC11

Network: 1

**Symbol information**

M9.2 Check start W1

Network: 2

**Symbol information**

DB26 WARNINGS PLC

Network: 3

A DBX ["Pointer WARNING quant."] MD16
 JC M002

Network: 4



Network: 5

BEU

Network: 6

M002: L "Supp. Quantity' WARNING" MW20
L 1
+I
T "Supp. Quantity' WARNING" MW20
M003: L "Pointer WARNING quant." MD16
L 1
+I
T "Pointer WARNING quant." MD16
L P#28.0
==I
JC M004
BEU
M004: L "Supp. Quantity' WARNING" MW20
T DB16.DBW 6
M001: S "Check start W1" M9.2
L 0
T "Pointer WARNING quant." MD16
T "Supp. Quantity' WARNING" MW20
BE