

Calibration Data Card

SHEAR ACCELEROMETER

MODEL # 356B18

SERIAL # 36120 (x axis)

SENSITIVITY 1013 mV/g
(109.3 mV/m/s²)

RANGE 0.5-3000 Hz

BIAS LEVEL 11.6 V

Date 10/28/04 By John Filizzola

For further information, please refer to the
accompanying calibration certificate.

PCB PIEZOTRONICS

3405 WALDEN AVE. DEPEW, NY 14045
800-684-0013

Calibration Data Card

SHEAR ACCELEROMETER

MODEL # 356B18

SERIAL # 36120 (y axis)

SENSITIVITY 1048 mV/g
(106.9 mV/m/s²)

RANGE 0.5-3000 Hz

BIAS LEVEL 11.6 V

Date 10/28/04 By John Filizzola

For further information, please refer to the
accompanying calibration certificate.

PCB PIEZOTRONICS

3405 WALDEN AVE. DEPEW, NY 14045
800-684-0013

Calibration Data Card

SHEAR ACCELEROMETER

MODEL # 356B18

SERIAL # 36120 (z axis)

SENSITIVITY 1023 mV/g
(104.2 mV/m/s²)

RANGE 0.5-3000 Hz

BIAS LEVEL 11.6 V

Date 10/28/04 By John Filizzola

For further information, please refer to the
accompanying calibration certificate.

PCB PIEZOTRONICS

3405 WALDEN AVE. DEPEW, NY 14045
800-684-0013